

DENON PDA-A10

故障内容 スピーカーターミナル破損、RCA入力破損

修理内容 スピーカー端子交換、RCA端子の修理

右側の端子の破損（スピーカーとRCA）



A photograph of a Denon POA-T10 amplifier unit. The top half shows the internal components, including a large silver heat sink, various electronic components, and a power transformer. The bottom half shows the front panel, which is black with silver lettering. It features two sets of speaker terminals labeled 'SPEAKER SYSTEMS' and 'SPEAKER IMPEDANCE'. A central remote control port is labeled 'REMOTE CONTROL'. The unit is marked 'MADE IN JAPAN' and includes a serial number 'DD675000 3C'.



スピーカー端子交換、RCA端子補強（足は作業のため未装着）



弊社では個人様・業者様を含め年間数百件の修理等を行っております。
修理等をお考えの方は [こちら](#) をクリックまたは、TEL 011-522-7822
オーディオ買取センター 修理係 までお問い合わせください。