


SANSUI AU- α 205

故障内容 ノイズ、異音がする、セレクターの接点接触不良

修理内容 セレクタースイッチの接点改善、パワーアンプ入力側のコンデンサー交換
(漏電のためノイズが出るため)

漏電のためトーン回路を調べる



This image shows the internal components of a power supply unit. The main brown printed circuit board (PCB) is populated with various electronic components, including electrolytic capacitors, resistors, and integrated circuits. A large black transformer is visible on the left side. A green daughterboard is connected to the main PCB. The unit is housed in a metal enclosure with a black fan cover on the right side.

弊社では個人様・業者様を含め年間数百件の修理等を行っております。
修理等をお考えの方は [こちら](#) をクリックまたは、TEL 011-522-7822
オーディオ買取センター 修理係 までお問い合わせください。